


ENGLISH HERITAGE



Philip George  
45 Main Road  
Little Gransden  
SANDY  
Bedfordshire  
SG19 3DL

Direct Dial: 0171 973 3277

March 1996

Dear Mr George

GREAT GRANSDEN CHURCH CLOCK AND BELLS

Mr Jeffries has passed your letter of 21 November to me to answer.

As you know I attended the meeting on Friday 1 December to discuss the rehangng of the church bells and the repositioning of the clock.

Subsequently I asked our civil engineer Graham Pledger to visit the church and look at the possibility of repairing the existing frame in situ and without the need to accommodate any additional bells.

Mr Pledger is satisfied that it would not be feasible to repair the existing frame sufficiently to allow bells to be rung full circle.

English Heritage would therefore not object to a grant for a faculty in principle to construct a new bell frame below the existing frame and to relocate the clock as necessary.

In due course we would be grateful to see detail drawings sharing the constructional details of the proposals. In our opinion these will be necessary in order to apply for a grant of faculty. Please let me know if I can be of any further assistance.

Yours sincerely

Paul Edwards  
Inspector of Historic Buildings  
Anglia Team